

# Problem Map,

Crescen Jute-mill Staff Colony



● Toilets in poor condition

● Inadequate number of dustbins

● Toilets without septic tanks

● Tubewells contain high amount of iron

■ Random waste dumping

— Solid waste dumping in drains

