

DISCUSSION TOPICS

FINDINGS

SANITATION







- BACK SIDE UNAUTHORIZED DWELLERS TOILET CONDITION IS VERY POOR.
- BATHING FACILITIES ARE POOR IN BACK PART.
- FEW HOUSEHOLDS ARE NOT AT ALL AWARE OF MAINTENANCE, SPECIALLY TENANTS.
- HANDWASH FACILITIES ARE NOT AVAILABLE EVERYWHERE.










DISCUSSION TOPICS

FINDINGS

SANITATION





TOILET POSITIONS IN RIHI PARA MAP (Showing hygiene condition)



DISCUSSION TOPICS

FINDINGS

HYGEINE









PEOPLE ARE NOT AWARE OF HYGEINE CONDITION YET.